

Safety Topic of the Month

Near Loss/ Near Miss Reporting

Richmond Refinery

11/1/2010



Near Loss/Near Miss Reporting

This Safety Topic of the Month covers:

- Recent serious injury which could have possibly been prevented by Near Loss/ Near Miss Reporting
- Why Near Loss/Near Miss Reporting is important
- How to report a Near Loss/ Near Miss
 - Impact ERM
 - Near Loss/ Near Miss "green" card
- Opportunity to discuss Near Loss/Near Miss in your area

© Chevron 2005 DOC ID



Injury at the Long Warf

On July 25th, an operator at the long wharf seriously injured his hand when it got caught between the rope and winch he was operating. During the investigation it was discovered that there had previously been near losses on this piece of equipment over the years including operators having their gloves caught and pulled off their hands, and yet no one reported these near losses...

IPS Control: 1988501 Contact Information:

Daryl Singleton CTN 242-1138 DADS@chevron.com Click Here for IPS Report Details



© Chevron 2005 DOC ID

Importance of Near Loss/ Near Miss Reporting



This injury may have been prevented if someone would have reported their near loss experience and had it properly investigated and corrective action taken.

Common Excuses for not reporting NLI's...

- > It is time consuming
- > Close calls are part of our business
- Nothing ever comes of it
- > It only happened this one time

What is your excuse? Would you be willing to report a NLI if you thought it might prevent you or a co-worker from losing the tips of 3 fingers?



How to report a Near Loss/Near Miss

Immediately notify your supervisor of a near loss/near miss.

Supervisors are responsible for properly investigating the near loss and entering it into the IMPACT ERM data base, if appropriate to do so.

Supervisors should follow up with the employee regarding the actions that are taken to eliminate or mitigate the risk.

The report and corrective action should be shared with other crews.

Near Loss/ Near Miss & Safety Suggestion Reporting Card – Green Card



Near Losses can also be reported using a Near Miss & Safety Suggestion Reporting card, otherwise known as a "Green Card". While these were originally intended for contractors, there is nothing wrong with employees using this process for reporting near misses or safety concerns, particularly if they want to remain anonymous. Cards are collected, prioritized by Supervisors, Field Safety Coordinators, Red Hats (during TA activity), and the TOP Office, and finally, "entered" into the IMPACT ERM,


Near Miss & Safety Suggestion Reporting Card					
lant		Time			
ocation		Date			
	Please Check One				
Slip/Trip/Fall	Open Flame Hot Work	Equipment			
Bump/Scrape/Pinch	Non-Open Flame Hot Work	Traffic			
Burn	Confined Space	Behavior			
Spill	Utility Connection	Radiation			
Tools	Chem Exposure	Electrica			
Crane Work	Housekeeping	LOTO			
Forklift	Leak Repair	Haz-Com			
PPE	Barricade Tape/Permitting	Other			

Mark the second	
Safety Suggestion:	
outery ouggestion.	
Company Name:	
Nama (Onlinest):	
Name (Optional):	

Near Loss/ Near Miss & Safety Suggestion Reporting Card - Green Card



In order to promote Near Loss/ Near Miss Reporting – an electronic version of the "Near Loss/ Near Miss Card" is available on the Refinery home page – on the Safety Tab and under "Tools". Instructions are included!



Criteria for Near Loss Reporting are still the same <u>Click Here for</u> **QNLR** Criteria <u>Announcement</u> from LPS Archives

7 © Chevron 2005 DOC ID



Near Loss/Near Miss Discussion

Are there Near Losses/Near Misses in our work areas that have not been addressed (similar to the long wharf)?

Another way to think about it... If your son or daughter came to work here, what would you tell them to be aware of, or watch out for?

How can we improve our reporting?

Closed Near Loss/ Near Miss Richmond Refinery, 9/1/10 - 10/20/10



				Potential	
	Division 0	Chart Description	Immediate Corrective Actions Taken	Severity	Location of Loss/Near Loss
Occurred	Division 9	Short Description	immediate Corrective Actions Taken	Classification	Loss/Near Loss
			·		Rich Plant
10/5				11.1	Protection
10/5	Department		extremely secure.	Level 1	Firehouse
	Cracking - D		Wood is being removed and replaced		Rich Crack
10/15	Crew	kickboard	with metal toe boards	Level 1	FCC SGRU
					Rich Maint
		Hose Modification			Facilities
10/10	DED / CED				Central Tool
10/18	RID/CIR	Discovered	proper personnel.	Level 2	Room
	Shutdown				Rich Crack
	Maintenance	Forklift caught	·		Crack Gen
	General	Electrical Pull Box	edges of the uneven surface of cover		Crack Area Ctrl
10/19	Support	Cover No. PB10	plate to prevent further incidents.	Level 1	Center
		In source t Not Cook	•		Diela I Admain
10/1	Planning	Margin calculation	errors.	Level 1	Rich Admin Building
	10/15 10/18 10/19	Occurred Division 9 A Crew - Fire Department Cracking - D Crew 10/15 RTD / CTR Shutdown Maintenance General Support Strategic & Facilities	Occurred Division 9 Short Description A Crew - Fire Department Department Equipment fell out Catalyst blow down line use caused smoldering of staging kickboard Hose Modification Violation of RI-613 Discovered Shutdown Maintenance General Support Forklift caught Electrical Pull Box Cover No. PB10 Strategic & Facilities Incorrect Net Cash	Occurred Division 9 Short Description Immediate Corrective Actions Taken When opening an apparatus door some equipment fell out Catalyst blow down line use caused smoldering of staging kickboard Hose Modification Violation of RI-613 Discovered Shutdown Maintenance General 10/19 Support Strategic & Facilities Facilities Forklift caught Electrical Pull Box Cover No. PB10 Strategic & Facilities When opening an apparatus door some equipment fell out extremely secure. An additional strap was installed to secure the struts in place. They are now extremely secure. Tagged hose out of service. Notified proper personnel. Will suggest that forklifts be driven with forks slightly higher than 6" guideline due to many uneven surfaces in plant areas. Will also have asphalt put around edges of the uneven surface of cover plate to prevent further incidents. Conducted an investigation to determine reasons for incorrect calculations and put controls in place to prevent further	Date Occurred Division 9 Short Description Immediate Corrective Actions Taken Severity Classification A Crew - Fire apparatus door some equipment fell out line use caused smoldering of staging kickboard with metal toe boards Level 1 10/15 Crew Shutdown Maintenance General 10/19 Support Forklift caught Facilities Facilities Incorrect Net Cash

© Chevron 2005 DOC ID



Review TOP Lessons Learned

Learning from our past incidents will help us prevent them in the future. Please take a few minutes now to review the TOP lessons learned.

TOP Lessons Learned